

Annexure D

BUILDING SAFETY CERTIFICATE

No. 373

Dated: 26/03/25

It is certified that the existing building MOUNT LITERA ZEE SCHOOL ... (name of the building or premises) at Damodarpur, Back of Collectorate, Lakhisarai.....

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>(G+2)</u>	<u>—</u>	<u>—</u>	<u>—</u>	<u>—</u>	<u>—</u>


The building is owned/occupied by MOUNT LITERA ZEE SCHOOL, LAKHISARAI (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Executive Engg (P.H.D.).. (Name of Department/ Govt.) on 24/03/25..... (date of inspection) in the presence of Pawan Kumar, Rampur Dumra, Marachi, Patna. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 26/03/25 for a period of One year..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. School is functioning in one Academic block only and security staff separately.
2. No addition and alteration be made in existing building.
3. All the staircase should be kept clear from any obstacles.
4. School Management will acquire fire safety certificates from fire development and follow the norms of the issued by respective department.

Issued on 26/03/25..... at Lakhisarai..... by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:


 कार्यपालक अभियंता
भवन प्रमडल, लखीसराय
MANOJ KUMAR
 Designation: ASSISTANT ENGG.

Name & Address of Department/ Office: BCD LKR.